

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 516 13TH ST		City: OREGON CITY			
USGS Quad Name: Oregon City		GPS	Latitude: 45 21 38 N		Longitude: 122 36 03 W
Township: 02S	Range: 02E	Section: 30	Block: 48	Lot: 1	Map #: 22E30DD Tax Lot #: 6400
Date of Construction: c. 1890	Historic Name:			Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling			Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Complex			Number of Stories: 2.0
Foundation Material: Brick		Structural Framing: Unknown			Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Aluminum multi-pane fixed; 1/1 wood double-			
Exterior Surface Materials Primary: Asbestos shingle		Secondary:		Decorative:	
Exterior Alterations or Additions/Approximate Date:		Single story addition to east façade; single story to north façade (porch enclosed) Asbestos shingle siding; partial window replacement; basement apartment added			
Number and Type of Associated Resources: None					
Integrity: Fair	Condition: Fair	Local Ranking:			National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old					
					
Description of Physical and Landscape Features:					
<p>This two story vernacular house has a complex plan due to additions and sits on a brick foundation. The gable roof is covered with composition shingles. The house is covered with asbestos ceramic shingles. Windows are primarily 1/1 wood double-hung with some fixed aluminum. Porch infill on the north façade created a new main entry door. Another single story addition is on the east façade creating a new secondary entrance.</p> <p>A free-standing carport is on the west side.</p>					
Statement of Significance:					

Researcher/Organization: Heather Goodson / HPNW			Date Recorded: 4/6/2002
Survey Form Page 1	Address: 516 13TH ST	Local Designation #	SHPO #