


# OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>314 MADISON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 09 N</b>	Longitude: <b>122 36 18 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>133</b>	Lot: <b>2x, 7x, 8x</b> Map #: <b>22E31DA</b> Tax Lot #: <b>4700</b>
Date of Construction: <b>1926</b>	Historic Name:		Historic Use or Function: <b>Domestic - single dwelling</b>
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>		Associated Archaeological Site: <b>Unknown</b>
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>6/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Lap</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>South side dug out and garage inserted underneath house; north side covered patio.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story bungalow is rectangular in plan and sits on a concrete block foundation with basement. The gable roof is covered in composition shingles and is pierced by a chimney. The house is covered with lap siding grounded by a water table and cap. Windows are primarily 6/1 wood double-hung. The gable roof entry porch has a decorative king post in the gable end and is supported by multiple, pressure treated posts. It has an open rail. An exterior chimney highlights the south elevation. A garage has been inserted under the house near the rear. Nice rhododendrons in northwest corner of yard.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>4/12/2002</b>
<b>Survey Form Page 1</b>	Address: <b>314 MADISON ST</b>	Local Designation # <b>SHPO #</b>