

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 813 5TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 14 N	Longitude: 122 36 16 W
Township: 02S	Range: 02E	Section: 31	Block: 110 Lot: 4x
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Complex	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung, aluminum sliders	
Exterior Surface Materials Primary: Lap		Secondary: Plywood	Decorative:
Exterior Alterations or Additions/Approximate Date: Gabled dormer added to east and south; porch enclosed			
Number and Type of Associated Resources: None			
Integrity: Fair		Condition: Fair	Local Ranking:
			National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This house sits under a gable roof with rectangular bays on the south and east sides of the house. The south bay was once an open porch, now enclosed with a bank of large aluminum sliding sash windows. These two gables feature open eaves with wide barge boards that are notched where there were once knee brackets. A second floor has been added to the house under a cross gable that has gable ends on the south and east sides of the house. A shed roof covers a lean-to addition on the east side of the eastern rectangular bay, and also features open eaves. The windows in the house are primarily aluminum sliding sashes, but a few original 1/1 double-hung wood sashes still exist. These windows have plain board trim on three sides and narrow sills, while the aluminum sashes have no exterior trim. The house is mostly clad with lap siding, but the eastern gable at the second floor is clad with plywood.			
Statement of Significance:			

Researcher/Organization: Alex McMurry / HPNW		Date Recorded: 3/25/2002	
Survey Form Page 1	Address: 813 5TH ST	Local Designation #	SHPO #