

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>919 5TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 12 N</b>	Longitude: <b>122 36 12 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>131</b> Lot: <b>4x, 3x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>14700</b>
Date of Construction: <b>c. 1910</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>9/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Asbestos shingle</b>		Secondary: <b>Plywood</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>One story wing to north; south porch railing</b>			
Number and Type of Associated Resources: <b>Garage to north (1)</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story house sits under a front gable roof with a small gable projecting out from the south side over the main entry to the house. This gable is supported by a pair of scroll cut brackets, and a new steel railing encircles the small porch. The main gable features enclosed eaves with decorative frieze and rake moldings above the asbestos ceramic shingle siding that covers the main body of the house. The windows are all double-hung wood sashes with divided upper lights and narrow trim moldings. A one story addition has been made to the north side of the house, clad with plywood and featuring a recessed porch on the east side where the eave is supported by decorative steel posts.  There is a one-car garage to the north of the house on Monroe Street.			
Statement of Significance:			

Researcher/Organization: <b>Alex McMurry / HPNW</b>		Date Recorded: <b>3/25/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>919 5TH ST</b>	Local Designation #	SHPO #