

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1119 5TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 09 N	Longitude: 122 36 05 W
Township: 02S	Range: 02E	Section: 31	Block: 159 Lot: 4x Map #: 22E31DA Tax Lot #: 1000
Date of Construction: c. 1915	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	

Architectural Classification(s): Bungalow	Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete	Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle	Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Drop	Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Window boxes added		
Number and Type of Associated Resources: None		

Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			

Description of Physical and Landscape Features:

This one story house sits under a front gable roof with a gabled rectangular bay on the south façade. The east side of the bay gable is bellcast and covers the recessed entry porch. The gables feature open eaves with wide barge boards and decorative knee brackets. The house rests on a poured concrete foundation, with a fully developed water table making the transition to the drop siding that covers the entire house. The windows in the house are all 1/1 double-hung wood sash with wide board surrounds on three sides and slightly projecting sills. The south windows have seen the addition of planter boxes. A brick chimney is located near the north end of the house, penetrating the roof at the ridge.

Statement of Significance:

Researcher/Organization: Alex McMurry / HPNW	Date Recorded: 3/25/2002
Survey Form Page 1 Address: 1119 5TH ST	Local Designation # SHPO #