

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>916 6TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 14 N</b>	Longitude: <b>122 36 10 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>131</b> Lot: <b>1x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>14200</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>L-shaped</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Fixed; aluminum sliders</b>	
Exterior Surface Materials Primary: <b>Vinyl</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Siding and windows replaced; porch enclosed; brick veneer added to foundation</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Poor</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This one story house sits under a gable roof with a large rectangular bay at the east end of the north façade under a second gable. The gables feature eaves enclosed with aluminum siding, and the west gable end retains its original knee brackets. The north side of the main gable, west of the bay, is an enclosed porch. The house is now entirely clad with vinyl siding, and all of the windows are aluminum sash replacements of the original windows. Awnings have been added over many of the windows.			
Statement of Significance:			
Researcher/Organization: <b>Alex McMurry / HPNW</b>			Date Recorded: <b>3/25/2002</b>
<b>Survey Form Page 1</b>	Address: <b>916 6TH ST</b>	Local Designation #	SHPO #