

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>419 5TH ST</b>				City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 20 N</b>		Longitude: <b>122 36 27 W</b>	
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>38</b>	Lot: <b>4</b>	Map #: <b>22E31AC</b> Tax Lot #: <b>3600</b>
Date of Construction: <b>1896</b>		Historic Name: <b>McDonough, Agnes and Martin, House</b>		Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>		*Current Name or Use: <b>Commerce - office</b>		Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Queen Anne</b>			Plan Type/Shape: <b>Complex</b>		Number of Stories: <b>2.0</b>
Foundation Material: <b>Stone</b>			Structural Framing: <b>Unknown</b>		Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>			Window Type/Material: <b>1/1, 4/1, 4/2 wood double-hung</b>		
Exterior Surface Materials Primary: <b>Asbestos shingle</b> Secondary: <b>Wood shingle</b> Decorative:					
Exterior Alterations or Additions/Approximate Date: <b>Asbestos siding covers original at first floor; rear porch enclosed</b>					
Number and Type of Associated Resources: <b>None</b>					
Integrity: <b>Good</b>		Condition: <b>Good</b>		Local Ranking: <b>Designated Historic Site</b> National Register Listed? <b>No</b>	
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old					
Description of Physical and Landscape Features:					
This two story Queen Anne sits under a gabled roof, with gables running both east-west and north-south. The gables typically cover octagonal bays that project out from the main body of the house. An octagonal porch under an octagonal hip roof is present at the southwest corner, where the roof is supported by slender turned columns with a simple balustrade enclosing the porch. The first floor level, above the stone foundation, which is said to be ballast from a ship from Maine, is clad with asbestos shingles. A decorative belt course separates the first and second floor above which the residence is clad with varying imbrication patterns including diamond, saw tooth, and rounded shingles. The shingles are slightly battered above the belt course. The windows in the house are all double-hung sashes, and are a mixture of 1/1, 4/1, and 4/2, with some 4/2, some with four-pane transom windows. The original porch on the north side of the house was enclosed, probably at the time the asbestos shingles were installed. Decorative features include scroll cut brackets at the octagonal bays just below the enclosed eaves, the bracketing and sunburst pattern in the gable ends, and the two interior corbelled chimneys.					
Statement of Significance:					

Researcher/Organization: <b>Alex McMurry / HPNW</b>			Date Recorded: <b>4/8/2002</b>		
<b>Survey Form Page 1</b>		Address: <b>419 5TH ST</b>		Local Designation #	
				SHPO #	