

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1015 6TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 14 N	Longitude: 122 36 06 W
Township: 02S	Range: 02E	Section: 31	Block: 139
Lot: 4x, 3x		Map #: 22E31AD	Tax Lot #: 9100
Date of Construction: c. 1924	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; fixed	
Exterior Surface Materials Primary: Round-edge drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Entry stairs replaced; aluminum storm windows added			
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Fair	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story bungalow sits under a front gable roof with open eaves, wide barge boards, and large knee brackets that penetrate the barge boards. A recessed porch is located at the southeast corner of the house, where the gable corner is supported by a large square column set on a solid balustrade. The house is clad above the fully developed water table with double drop siding, finished with corner moldings. The foundation is skirted with wider drop siding. The windows are primarily 1/1 double-hung wood sash with aluminum storm windows, but a large fixed pane with a five-pane transom exists at the porch. The windows typically feature board trim with narrow sills and small apron moldings. A small porch is located on the east side of the house, just north of a large brick chimney. This porch is covered by a shed roof extension of the main gable, supported by slender wood columns.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 1015 6TH ST	Local Designation #	SHPO #