

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1113 6TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 12 N	Longitude: 122 36 03 W
Township: 02S	Range: 02E	Section: 31 Block: 158	Lot: 4x, 3x Map #: 22E31AD Tax Lot #: 8000
Date of Construction: c. 1900	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular / Queen Anne		Plan Type/Shape: Complex	Number of Stories: 1.5
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Cross gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; aluminum sliding	
Exterior Surface Materials Primary: Lap		Secondary: Vertical T&G	Decorative: Wood shingle
Exterior Alterations or Additions/Approximate Date: Limited siding and window replacement; new entry stairs			
Number and Type of Associated Resources: None			
Integrity: Fair Condition: Fair		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story house sits under a cross gable roof with an extension of the south gable over the recessed entry porch at the southwest corner of the house. The gables feature enclosed eaves with wide frieze and rake boards, with the exception of the south gable end that features wood shingles above the eave line. This gable end also features decorative spindle work above the second floor window. The house is primarily clad with horizontal lap siding and drop siding finished with cornerboards, but the first floor level of the south gable is clad with vertical tongue and groove siding. A small spindle work belt course separates this siding from the lap siding above. The windows are primarily 1/1 double-hung wood sash, but the south end windows have been replaced with aluminum sliding sashes. The windows typically feature board trim, some with projecting hood moldings. The replacement windows have no exterior trim.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 1113 6TH ST	Local Designation #	SHPO #