

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1218 6TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 09 N	Longitude: 122 36 00 W
Township: 02S	Range: 02E	Section: 31 Block: 163 Lot: 1, 2	Map #: 22E31DA Tax Lot #: 1400
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Gable added to east			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Poor		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This modest bungalow sits under a front gable roof with a full width hipped porch on the primary façade. The porch roof is supported by a pair of tapered square columns set on a solid wood balustrade. The balustrade, like the rest of the house, is clad with double drop siding finished with cornerboards. Both the main gable and the porch hip feature open eaves, and the porch has a wide blank frieze beneath the rafter tails. The windows in the house are predominantly 1/1 double-hung wood sash with wide board surrounds. A central brick chimney penetrates the ridge near the south end of the house, and a newer stove pipe is located just northwest of the brick chimney. A gable roof has been added to the east side of the house over the rear entrance steps and a small porch.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 1218 6TH ST	Local Designation #	SHPO #