

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>802 7TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 19 N</b>	Longitude: <b>122 36 12 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>111</b> Lot: <b>7x, 6x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>10700</b>
Date of Construction: <b>c. 1920</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Commerce - office</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Bellcast hip / Composition shingle</b>		Window Type/Material: <b>Aluminum sliders; fixed</b>	
Exterior Surface Materials Primary: <b>Plywood</b>		Secondary:	Decorative: <b>Battens</b>
Exterior Alterations or Additions/Approximate Date: <b>Ramps; staircases; plywood surfacing; full window replacement</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Poor</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This one story house has lost almost all of its integrity over the years on its way to becoming an office. The bellcast hipped roof is covered in composition shingles. The walls are covered with plywood panels and battens, and adorned with modillions. Windows are primarily aluminum sliders. The front entry porch is covered with a shed roof and is accessed by steps and a ADA ramp. A side entry has a small uncovered porch.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>802 7TH ST</b>	Local Designation #	SHPO #