

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>511 1ST ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 09 N</b>	Longitude: <b>122 36 35 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>83</b>
Lot: <b>4x, 3x</b>		Map #: <b>22E31DB</b>	Tax Lot #: <b>5800</b>
Date of Construction: <b>c. 1922</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Post and beam</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>1/1 vinyl double-hung</b>	
Exterior Surface Materials Primary: <b>Channel drop</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>French door entry; porch rebuilt</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story vernacular house on the alley is rectangular in plan. The side gable roof is covered in composition shingles. The house is covered with channel drop siding ground by vertical wood foundation skirting. Windows are primarily 1/1 vinyl double-hung. The hip roofed entry porch has narrow posts and open rail. The main entry doors are double French doors. An early one story ell is on the rear (south) façade.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>4/6/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>511 1ST ST</b>	Local Designation #	SHPO #