

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1111 7TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 15 N</b>	Longitude: <b>122 36 01 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>157</b> Lot: <b>4x</b>	Map #: <b>22E31AD</b> Tax Lot #: <b>6800</b>
Date of Construction: <b>c. 1900</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Front gable and wing</b>		Plan Type/Shape: <b>T-shaped</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Large wood fixed; 3/1 &amp; 1/1 wood double-hun</b>	
Exterior Surface Materials Primary: <b>Drop</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Early additions to rear</b>			
Number and Type of Associated Resources: <b>Garage to SE (1)</b>			
Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story front-gable-and-wing T-shaped plan and sits on a concrete foundation. The -gable roof is covered in composition shingles. The walls are clad in drop siding grounded by a water table. Windows are primarily large fixed pane with ribbon transoms. The hipped-roof front porch is supported by truncated posts on a solid rail, and there are two entry doors off the front porch. The front door is bungalow-era.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>5/10/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1111 7TH ST</b>	Local Designation #	SHPO #