

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1115 13TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 30 N	Longitude: 122 35 44 W
Township: 02S	Range: 02E	Section: 32 Block: 151 Lot: 4	Map #: 22E32BB Tax Lot #: 2100
Date of Construction: c. 1915	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Metal shingle		Window Type/Material: 4/4 wood double-hung; wood fixed	
Exterior Surface Materials Primary: Cementitious lap		Secondary: Channel drop	Decorative:
Exterior Alterations or Additions/Approximate Date: Front porch rebuilt; cementitious lap siding, 2000			
Number and Type of Associated Resources: Garage to west (1)			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
<p>This one story bungalow has a rectangular plan and sits on a poured concrete foundation. The gable roof is covered with metal shingles, has a decorative rake board, shaped eave brackets, and is pierced by a chimney. The house is covered with lap siding, with channel drop siding in the gables. Windows are primarily 4/4 wood double-hung. The gable roof entry porch also has decorative rake board and eave brackets, new columns and small gable detail. There is early porch infill on the west side. The front door was replaced in the 1990s. A small addition to the east façade has a gable roof.</p> <p>A detached garage, contemporary with the house, lies to the west.</p>			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 1115 13TH ST	Local Designation #	SHPO #