

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1220 13TH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 27 N</b>	Longitude: <b>122 35 42 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b> Block: <b>170</b>	Lot: <b>1x, 2x</b> Map #: <b>22E32BB</b> Tax Lot #: <b>6500</b>
Date of Construction: <b>c. 1910</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Square</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Aluminum sliders; vinyl sliders</b>	
Exterior Surface Materials Primary: <b>Round-edge drop</b>		Secondary: <b>Beadboard</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Full window replacement with aluminum and vinyl sliders; porch structure incompatibly rebuilt.</b>			
Number and Type of Associated Resources: <b>1990s garage to west (1)</b>			
Integrity: <b>Fair</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story bungalow has a rectangular plan and sits on a poured concrete foundation with basement. The gable roof is covered with composition shingles, has decorative rake board and eave brackets, and is pierced by a chimney. The house is covered with round-edge drop siding grounded by a water table with cap. Windows are primarily aluminum and vinyl sash sliders. The gable roof entry porch also has decorative rake board and eave brackets, square columns and open rail.  A 1990's detached, single car garage is on the west side.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>4/12/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1220 13TH ST</b>	Local Designation #	SHPO #