

OREGON CITY HISTORIC RESOURCE SURVEY FORM

| | | | |
|---|--|--|--|
| Street Address: 107 CENTER ST | | City: OREGON CITY | |
| USGS Quad Name: Oregon City | | GPS Latitude: 45 21 09 N | Longitude: 122 36 38 W |
| Township: 02S | Range: 02E | Section: 31 | Block: 82 |
| Lot: 3x | | Map #: 22E31CA | Tax Lot #: 1300 |
| Date of Construction: c. 1922 | Historic Name: | Historic Use or Function: Domestic - single dwelling | |
| Grouping or Cluster Name: NA | *Current Name or Use: Domestic - single dwelling | Associated Archaeological Site: Unknown | |
| Architectural Classification(s): Bungalow | | Plan Type/Shape: Rectangle | Number of Stories: 1.0 |
| Foundation Material: Concrete block | | Structural Framing: Unknown | Moved? No |
| Roof Type/Material: Gable / Composition shingle | | Window Type/Material: 1/1 wood double-hung | |
| Exterior Surface Materials Primary: Round-edge drop | | Secondary: | Decorative: |
| Exterior Alterations or Additions/Approximate Date: Aluminum slider window in gable; Front entry door replaced (date unknown) | | | |
| Number and Type of Associated Resources: None | | | |
| Integrity: Excellent | Condition: Excellent | Local Ranking: | National Register Listed? No |
| Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old | | | IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH |
| Description of Physical and Landscape Features: | | | |
| This simple c. 1922 bungalow house has a gable roof, with a minimal rake board and a gabled front porch supported by triangular brackets. The exterior is clad with horizontal round edge drop wood siding. The front entrance porch retains the tongue and groove flooring and is supported by 4x4 wood porch posts with square spindles on the balustrade. The windows are typical of the bungalow style with original 6-pane windows located at the rear of the house. 1/1 aluminum windows exist on the front elevation with a aluminum slider in the gable of the main facade. Alterations include a non-historic entrance door with a screen. | | | |
| Statement of Significance: | | | |
| | | | |

| | | | |
|--|-------------------------------|---------------------------------|--------|
| Researcher/Organization: Christy Fockler / HPNW | | Date Recorded: 4/12/2002 | |
| Survey Form Page 1 | Address: 107 CENTER ST | Local Designation # | SHPO # |