

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 111 CENTER ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 10 N	Longitude: 122 36 37 W
Township: 02S	Range: 02E	Section: 31	Block: 82
Lot: 3x		Map #: 22E31CA	Tax Lot #: 1200
Date of Construction: c. 1906	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Unknown		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Vinyl	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding, some window replacement			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This front gabled transitional style house has eave brackets and a full width front porch. The porch has a hipped roof and columns with capitals and a band around the base. A knee wall surrounds the porch and a large picture window is north of the door. Two narrow 1/1 windows covered with aluminum screens punctuate the front elevation gable. Vertical groove plywood skirts the porch and tongue and groove decking lies on top. The house is sided in asbestos ceramic shingles. A chimney projects from the roof ridge. The north side elevation has two single and one double tall, narrow windows that appear to be original. A picket fence surrounds the front yard. There is an alley on the north side.			
Statement of Significance:			

Researcher/Organization: Rebecca Nielsen / HPNW		Date Recorded: 5/17/2002	
Survey Form Page 1	Address: 111 CENTER ST	Local Designation #	SHPO #