

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 113 CENTER ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 11 N	Longitude: 122 36 37 W
Township: 02S	Range: 02E	Section: 31 Block: 82 Lot: 2	Map #: 22E31CA Tax Lot #: 1100
Date of Construction: c. 1908	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: L-shaped	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Asbestos ceramic shingles; porch incompatible; shed addition with aluminum siding to northwest			
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story bungalow has a L-shaped plan and sits on a concrete foundation. The gable roof is covered in composition shingles with decorative brackets at the eaves and pointed bargeboard. The walls are covered with asbestos ceramic shingles. Windows are primarily 1/1 wood double-hung. The entry porch is covered with a gable roof supported by wrought iron posts. There are wrought iron railings and a concrete floor and steps. There is a shed addition with aluminum siding to the northwest.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 113 CENTER ST	Local Designation #	SHPO #