

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>118 CENTER ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 10 N</b>	Longitude: <b>122 36 35 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>83</b>
Lot: <b>7x</b>		Map #: <b>22E31DB</b>	Tax Lot #: <b>5400</b>
Date of Construction: <b>c. 1917</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Picture; 1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Round-edge drop</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Concrete porch floor, n.d.; wrought iron porch posts and railing, n.d.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story bungalow has a rectangular plan and sits on a poured concrete foundation. The gable roof is covered with composition shingles and has eave returns. The house is covered in lapped siding grounded by a water table with cap. Windows are primarily picture and 1/1 wood double-hung. The gabled roof front entry porch is supported by wrought iron posts and has wrought iron railing. The floor has been replaced with a poured concrete floor.			
Statement of Significance:			
Researcher/Organization: <b>Heather Goodson / HPNW</b>			Date Recorded: <b>4/6/2002</b>
<b>Survey Form Page 1</b>	Address: <b>118 CENTER ST</b>	Local Designation #	SHPO #