

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 121 CENTER ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 11 N	Longitude: 122 36 37 W
Township: 02S	Range: 02E	Section: 31 Block: 82 Lot: 1	Map #: 22E31CA Tax Lot #: 1000
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 vinyl double-hung	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Shed roof addition on west (rear) façade; asbestos ceramic shingles; faux shutters; full window replacement			
Number and Type of Associated Resources: Period garage to southwest; new workshop to southwest (2)			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This one story side gabled bungalow has a rectangular plan and sits on a concrete foundation. The gable roof is covered with composition shingles, has exposed rafter tails obscured by gutters and decorative eave brackets. The house is covered in asbestos ceramic shingles. Windows are 1/1 wood double-hung with decorative shutters flanking them. The gabled roof front entry porch is supported by brackets and has wrought iron railing. The floor and steps are poured concrete. A shed roof addition is on the west (rear) façade. A period garage, covered in asbestos shingles, is southwest of the house. A new workshop is on the south side of the house.			
Statement of Significance:			
Researcher/Organization: Heather Goodson / HPNW			Date Recorded: 5/10/2002
Survey Form Page 1	Address: 121 CENTER ST	Local Designation #	SHPO #