

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 616 11TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 32 N	Longitude: 122 36 07 W
Township: 02S	Range: 02E	Section: 31 Block: 67 Lot: 1x	Map #: 22E31AA Tax Lot #: 5800
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 vinyl double-hung	
Exterior Surface Materials Primary: Channel drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Enclosed portion of front porch; full window replacement; mock shutters; basement apartment with front entry			
Number and Type of Associated Resources: Retaining wall garage to NE (1)			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story vernacular house has a rectangular plan and sits on a concrete block foundation with basement. The gable roof is covered with composition shingles and has decorative eave brackets. The house is covered with drop siding and decorative shutters flank the windows. Windows are primarily 1/1 double-hung with hoods. Half of the front entry porch has been enclosed. There are turned porch posts with a recently constructed railing at the entry. There is a hooded entry on the west side. Two car garage built into hill and retaining wall in front of the house.			
Statement of Significance:			
Researcher/Organization: Heather Goodson / HPNW			Date Recorded: 4/12/2002
Survey Form Page 1	Address: 616 11TH ST	Local Designation #	SHPO #