

### OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>208 CENTER ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 12 N</b>	Longitude: <b>122 36 33 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>58</b> Lot: <b>6x</b>	Map #: <b>22E31AC</b> Tax Lot #: <b>13700</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Jerkinhead / Composition shingle</b>		Window Type/Material: <b>20/1 fixed; 8/1 and 1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Bevel (lap)</b>		Secondary: <b>Brick</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Brick porch</b>			
Number and Type of Associated Resources: <b>Period garage to northeast (1)</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This 1-1/2 story side-jerkinhead bungalow has a rectangular plan and sits on a poured concrete foundation. The jerkinhead roof is covered in composition shingles, has eave returns and is pierced by two chimneys. The house is covered with lap siding grounded by a water table with cap. Windows are multi-pane over one and one over one wood double-hung. The south façade has a square bay. The entry porch is supported by brick columns and has a brick knee wall.  A period garage, with jerkinhead roof and full returns, sits to the northeast of the house.			
Statement of Significance:			
Researcher/Organization: <b>Heather Goodson / HPNW</b>			Date Recorded: <b>5/10/2002</b>
<b>Survey Form Page 1</b>	Address: <b>208 CENTER ST</b>	Local Designation #	SHPO #