

OREGON CITY HISTORIC RESOURCE SURVEY FORM

| | | | |
|---|--|--|--|
| Street Address: 118 CLINTON ST | | City: OREGON CITY | |
| USGS Quad Name: Oregon City | | GPS Latitude: 45 20 57 N | Longitude: 122 36 52 W |
| Township: 02S | Range: 02E | Section: 31 Block: 78 Lot: 8 | Map #: 22E31CA Tax Lot #: 8500 |
| Date of Construction: c. 1918 | Historic Name: | Historic Use or Function: Domestic - single dwelling | |
| Grouping or Cluster Name: NA | *Current Name or Use: Domestic - single dwelling | Associated Archaeological Site: Unknown | |
| Architectural Classification(s): Bungalow | | Plan Type/Shape: Rectangle | Number of Stories: 1.0 |
| Foundation Material: Concrete | | Structural Framing: Unknown | Moved? No |
| Roof Type/Material: Gable / Composition shingle | | Window Type/Material: Aluminum sliders | |
| Exterior Surface Materials Primary: Metal | | Secondary: | Decorative: |
| Exterior Alterations or Additions/Approximate Date: Full siding and window replacement. | | | |
| Number and Type of Associated Resources: None | | | |
| Integrity: Fair Condition: Good | | Local Ranking: | National Register Listed? No |
| Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity | | |  |
| Description of Physical and Landscape Features: | | | |
| This modest bungalow sits under a front gable roof with a small rectangular bay on the south side that houses the main entrance to the house. This bay is fully enclosed, and is covered by a small gable roof. The main gable features deep open eaves and knee brackets that penetrate the wide barge boards. The house is clad with aluminum siding, and has seen the replacement of all of its windows with aluminum sliding sashes. The windows have no exterior trim. A brick chimney is centrally located in the house, which rests on a poured concrete foundation. | | | |
| Statement of Significance: | | | |
| | | | |

| | | | |
|---|--------------------------------|---------------------------------|--------|
| Researcher/Organization: Alex McMurry / HPNW | | Date Recorded: 3/18/2002 | |
| Survey Form Page 1 | Address: 118 CLINTON ST | Local Designation # | SHPO # |