

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 506 ELM ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 35 N	Longitude: 122 36 08 W
Township: 02S	Range: 02E	Section: 31 Block: 49 Lot: 2x	Map #: 22E31AA Tax Lot #: 3300
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Bellcast hip / Composition shingle		Window Type/Material: 1/1 double-hung	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding replaced, storm windows added.			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This house sits under a bellcast hip roof, with a low hip over the entry porch on the southeast corner. The porch hip is supported by large square columns beneath a wide blank frieze. The hips both feature enclosed eaves with block modillions that extend out to the eave edge. The house has been clad with asbestos shingles over the original beveled lap siding that is still visible at the inside of the porch. The windows are all 1/1 double-hung wood sash with plain board trim on three sides and projecting sills with small apron moldings. All of the windows have seen the addition of aluminum storm windows. A concrete block chimney is located near the north end of the house, which also features a parged concrete foundation.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/26/2002
Survey Form Page 1	Address: 506 ELM ST	Local Designation #	SHPO #