

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>818 JACKSON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 18 N</b>	Longitude: <b>122 35 55 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b> Block: <b>166</b> Lot: <b>7</b>	Map #: <b>22E32BC</b> Tax Lot #: <b>7600</b>
Date of Construction: <b>1928</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Minimal Traditional</b>		Plan Type/Shape: <b>Square</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>6/1 wood double-hung with fixed aluminum st</b>	
Exterior Surface Materials Primary: <b>Wood shingle</b>		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Side door enclosure on south elevation; siding; shutters</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b>	Condition: <b>Good</b>	Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This Minimal Traditional side-gable house c.1928 is eaveless and features wavy horizontal siding in the gable entry hood. Narrow steps lead from the sidewalk, which is fronted by a low concrete retaining wall. The 6/1 double-hung windows appear in groupings. The front door features applied arch molding. The siding is wood shingle, and there are faux shutters. There is a metal railing at the concrete stoop. The side entry features a non-original enclosure.			
Statement of Significance:			

Researcher/Organization: <b>Marti Gerdes / HPNW</b>		Date Recorded: <b>5/11/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>818 JACKSON ST</b>	Local Designation #	SHPO #