

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1312 JACKSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 30 N	Longitude: 122 35 42 W
Township: 02S	Range: 02E	Section: 32	Block: 171
Lot: x7, x8		Map #: 22E32BB	Tax Lot #: 1300
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Aluminum sliders	
Exterior Surface Materials Primary: Metal		Secondary: Brick	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding; porch extensions off west and east elevations			
Number and Type of Associated Resources: None			
Integrity: Poor		Condition: Fair	Local Ranking:
			National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This one-story, rectangular vernacular house c.1920 consists of a front gable with gabled porch, wrought-iron columns, and brick on half of the front façade. A sliding glass door faces the street from the solid concrete porch. Tapered concrete steps lead to the house from the sidewalk. The windows are primarily aluminum sliders. There are porch extensions off the west and east elevations.			
Statement of Significance:			
The house's integrity is poor, as is its condition.			

Researcher/Organization: Marti Gerdes / HPNW		Date Recorded: 5/11/2002	
Survey Form Page 1	Address: 1312 JACKSON ST	Local Designation #	SHPO #