

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 106 JEFFERSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 04 N	Longitude: 122 36 27 W
Township: 02S	Range: 02E	Section: 31	Block: NA Lot: NA Map #: 22E31DB Tax Lot #: 1900
Date of Construction: 1936	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Tract		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Aluminum sliders	
Exterior Surface Materials Primary: Vertical groove plywo		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Resided; full window replacement; porch addition to front; side shed cover addition; foundation possibly rebuilt/raised			
Number and Type of Associated Resources: None			
Integrity: Poor	Condition: Fair	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This single story vernacular residence has a rectangular plan with a gable addition to the rear and has been greatly altered. It sits on a concrete block foundation that was laid over a rock wall/foundation and is clad in vertical groove plywood. The gabled roof has exposed rafters and is covered with composition shingling. The windows are primarily aluminum sliding, a full window replacement. There is a wooden front deck with wooden stairs half way to the ground, then buttressed concrete stairs the rest of the way down. The site is heavily sloped and appears to be suffering from groundwater drainage problems.			
Statement of Significance:			

Researcher/Organization: Carin Petersen / HPNW		Date Recorded: 5/11/2002	
Survey Form Page 1	Address: 106 JEFFERSON ST	Local Designation #	SHPO #