

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 303 JEFFERSON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 10 N	Longitude: 122 36 23 W
Township: 02S	Range: 02E	Section: 31 Block: 105 Lot: 4	Map #: 22E31AC Tax Lot #: 8200
Date of Construction: c. 1900	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Vernacular		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Asbestos shingle Secondary: Vertical groove plywo Decorative:			
Exterior Alterations or Additions/Approximate Date: front porch; side porch; possible extension of entire left side and extension of gable			
Number and Type of Associated Resources: None			
Integrity: Fair Condition: Excellent		Local Ranking:	National Register Listed? No
Potentially Eligible: <input checked="" type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This house, which sits directly on the end of its lot closest to the street, appears quite lopsided. An addition was cantilevered on the south side of the structure which would account for the longer gable on that side and the additional side entry at this point. A shed roof porch that stops where original house width stops covers the front entry. Vertical siding now makes up the skirt of the porch and the railing. Metal storm windows have been added to the 1/1 wood double-hung, and asbestos ceramic shingle siding covers the house. A wide rake board and frieze detail how the walls meet the roof.			
Statement of Significance:			

Researcher/Organization: Joe Snider / HPNW		Date Recorded: 5/30/2002	
Survey Form Page 1	Address: 303 JEFFERSON ST	Local Designation #	SHPO #