

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1103 JQ ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 26 N	Longitude: 122 35 53 W
Township: 02S	Range: 02E	Section: 32	Block: 144 Lot: 4x Map #: 22E32BB Tax Lot #: 7700
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	

Architectural Classification(s): Bungalow	Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete	Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle	Window Type/Material: 1/1 single-hung wood	
Exterior Surface Materials Primary: Asbestos shingle		Secondary: Decorative:
Exterior Alterations or Additions/Approximate Date: Shutters added; some vinyl window replacements, asbestos ceramic shingle siding		
Number and Type of Associated Resources: Garage on north side (1)		

Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			

Description of Physical and Landscape Features:

This one-story bungalow has a side-facing gable roof sheathed in composition shingles. It has a simple rectangular and sits on a poured concrete foundation. The house is clad in face-nailed asbestos ceramic siding. The windows on the front façade are 1/1 single-hung wood, with the upper sash being smaller than the lower. Decorative shutters have been added. Many of the windows on the other three elevations have been replaced with vinyl ones. There are brackets on the gable ends. The front entry vestibule is recessed into the house, but has no porch.

There is a small single detached garage on the north side.

Statement of Significance:

Researcher/Organization: Jessica Engeman / HPNW	Date Recorded: 4/6/2002
Survey Form Page 1 Address: 1103 JQ ADAMS ST	Local Designation # SHPO #