

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1107 JQ ADAMS ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 27 N	Longitude: 122 35 52 W
Township: 02S	Range: 02E	Section: 32 Block: 144 Lot: 3	Map #: 22E32BB Tax Lot #: 7600
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Minimal Traditional		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Front porch filled in. Wing addition to the south in 1960s.			
Number and Type of Associated Resources: Free-standing carport (1)			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
<p>The house is a minimal traditional with a broken pitch gable roof. The original round-edge drop siding has been covered with wood shingles. The porch was filled in c.1960 at the same time an addition to the south was added, and the entire house was covered with wood shingles. There are currently metal storm windows on the windows and inoperable faux shutters flank the windows. A small concrete retaining wall which levels the yard from the grade of the street has integrated steps up into the yard.</p> <p>There is a free-standing carport to the northwest of the house.</p>			
Statement of Significance:			
Researcher/Organization: Joe Snider / HPNW			Date Recorded: 5/10/2002
Survey Form Page 1	Address: 1107 JQ ADAMS ST	Local Designation #	SHPO #