

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>927 MADISON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 26 N</b>	Longitude: <b>122 36 02 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>114</b> Lot: <b>1</b>	Map #: <b>22E31AA</b> Tax Lot #: <b>8200</b>
Date of Construction: <b>c. 1900</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Vernacular</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.5</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Large picture; 1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Wood shingle</b>		Secondary: <b>Lap</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Additions to rear, c.1950s; eaves cut off</b>			
Number and Type of Associated Resources: <b>Stuccoed garage in hill at northeast corner (1)</b>			
Integrity: <b>Fair</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This 1-1/2 vernacular house is rectangular in plan and sits on a concrete foundation. The eaveless, gable roof is covered in composition shingles and is pierced by a chimney. The chimney is an exterior stuccoed chimney on the south side. There are chamfered corners on the north and south gable wings. The house is covered with wood shingles and lap siding in the gable ends. Windows are primarily large picture windows. The entry porch is supported by narrow posts and has a wrought iron railing.  The garage is detached and one level lower than the house.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>4/6/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>927 MADISON ST</b>	Local Designation #	SHPO #