

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>1318 MADISON ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 36 N</b>	Longitude: <b>122 35 50 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>32</b> Block: <b>123</b> Lot: <b>8x</b>	Map #: <b>22E32BB</b> Tax Lot #: <b>4400</b>
Date of Construction: <b>c. 1920</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>1/1 wood double-hung</b>	
Exterior Surface Materials Primary: <b>Wood shingle</b>		Secondary: <b>Brick</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Porch and staircase rebuilt, c.1980s; brick foundation façade across front; wood shingle siding covers original siding.</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Good</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story bungalow is rectangular in plan and sits on a foundation with an original garage underneath. The gable roof is covered in composition shingles. There is an exterior side chimney. The house is covered with wood shingles. Brick has been added to the foundation on front façade. Windows are primarily 1/1 wood double-hung. The hip roof entry porch is supported by narrow posts and has an open rail.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>5/10/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>1318 MADISON ST</b>	Local Designation #	SHPO #