

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 513 MONROE ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 13 N	Longitude: 122 36 11 W
Township: 02S	Range: 02E	Section: 31 Block: 131 Lot: 2x	Map #: 22E31AD Tax Lot #: 14300
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Square	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 vinyl	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Patio, west shed roof addition, fiberglass siding, windows			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input checked="" type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
Two front gables with eave brackets present themselves to the street in this rectangular plan house. The smaller projecting gable has a single picture window. The larger recessed gable is the main mass of the house and has a small fixed window in the gable and the front door with a window beside it. The hooded front gable porch is an extension of the most extended front gable. All the windows are different: some vinyl, some wood, some metal. There is an enclosed back porch on the west side. A concrete block retaining wall runs east to west along the alley to the flat roof detached garage.			
Statement of Significance:			
Researcher/Organization: Rebecca Nielsen / HPNW			Date Recorded: 4/12/2002
Survey Form Page 1	Address: 513 MONROE ST	Local Designation #	SHPO #