

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 516 MONROE ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 13 N	Longitude: 122 36 09 W
Township: 02S	Range: 02E	Section: 31 Block: 138 Lot: 7	Map #: 22E31AD Tax Lot #: 15000
Date of Construction: c. 1924	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 aluminum double-hung	
Exterior Surface Materials Primary: Drop		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Altered porch, date unknown; window alteration			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Excellent	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
<p>This c.1924 bungalow has a rectangular plan with a multi-gabled roof and a full extension shed dormer at the upper level of the south façade. Decorative brackets with shaped ends embellish the eaves. A front facing gable with decorative brackets is supported by non-historic, truncated, pressure-treated wood porch columns. Decorative latticework surrounds the porch skirt. Non-historic aluminum sliding window are present in some locations, while 1/1 double-hung aluminum windows are typical of all elevations. A fixed aluminum picture window is present on the front elevation. A manicured hedge exists at the front façade flanking the entrance walkway.</p> <p>A detached garage with original hinged doors is present to the southeast of the structure. Alterations include the shed wall dormer addition and front porch modification.</p>			
Statement of Significance:			
Researcher/Organization: Christy Fockler / HPNW			Date Recorded: 4/12/2002
Survey Form Page 1	Address: 516 MONROE ST	Local Designation #	SHPO #