

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 1113 MONROE ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 29 N	Longitude: 122 35 55 W
Township: 02S	Range: 02E	Section: 32	Block: 125 Lot: 2x Map #: 22E32BB Tax Lot #: 8500
Date of Construction: c. 1910	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow / Altered		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: Vinyl	
Exterior Surface Materials Primary: Channel drop		Secondary: Vertical groove plywo	Decorative:
Exterior Alterations or Additions/Approximate Date: North and south side square additions added with no windows			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
The front-gabled, one-story house has a rake board and small gabled hood with brackets over the front door. The visible windows appear to be vinyl, including the front elevation window. A square vent cuts through the front gable. Square additions without windows protrude from the north and south end of the house towards the rear. Another house, approximately from the 1920s, is built directly behind this house and is possibly connected. The roof is new and there is deck on the east side. There are two types of siding: vertical and horizontal. Siding is vertical in the gable and in the upper half of the south elevation.			
Statement of Significance:			

Researcher/Organization: Rebecca Nielsen / HPNW		Date Recorded: 4/6/2002	
Survey Form Page 1	Address: 1113 MONROE ST	Local Designation #	SHPO #