

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 815 VAN BUREN ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 17 N	Longitude: 122 35 53 W
Township: 02S	Range: 02E	Section: 32 Block: 166 Lot: 2x	Map #: 22E32BC Tax Lot #: 8100
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Jerkinhead / Composition shingle		Window Type/Material: 6/1 wood single-hung	
Exterior Surface Materials Primary: Lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Shed roof porch entry on rear			
Number and Type of Associated Resources: None			
Integrity: Excellent Condition: Excellent		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This bungalow with craftsman detailing sits with very little setback almost directly on the sidewalk. It is also on the same level as the sidewalk. A jerkinhead roof runs parallel to the street, and its wide overhanging eaves are supported by brackets. Stairs with a metal hand rail lead to a small entry porch on the street that also has a clipped gable, and is detailed with exposed rafter ends. Beveled lap siding covers the house, and very little appears to have been altered, with the exception of a shed roof entry porch on the rear. A water table brings the siding and the concrete foundation together. 6/1 wood double-hung windows punctuate the house.			
Statement of Significance:			

Researcher/Organization: Joe Snider / HPNW		Date Recorded: 5/22/2002	
Survey Form Page 1	Address: 815 VAN BUREN ST	Local Designation #	SHPO #