

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 914 VAN BUREN ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 19 N	Longitude: 122 35 49 W
Township: 02S	Range: 02E	Section: 32	Block: NA Lot: NA Map #: 22E32BC Tax Lot #: 3200
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Altered		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Hip / Composition shingle		Window Type/Material: Fixed picture	
Exterior Surface Materials Primary: Lap		Secondary: Brick	Decorative:
Exterior Alterations or Additions/Approximate Date: Siding is clearly not original; significant additions to back; large dormer added in back; porch enclosed in front			
Number and Type of Associated Resources: None			
Integrity: Poor Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This house sits slightly above the street with a yard in front that is held in place by a river rock retaining wall installed c. 1945. The house has been so significantly altered that a determination of style cannot be accurately made. There really is no part of the original house visible. Despite its c. 1900 construction date, the house looks almost as though it is a 1950s ranch house. Significant alterations on all four facades have been made, including a large dormer in the back. Windows are primarily large single pane fixed. There is brick detailing at the entry porch, though it is merely surfacing. Other surfacing includes wood lap siding.			
Statement of Significance:			

Researcher/Organization: Joe Snider / HPNW		Date Recorded: 5/22/2002	
Survey Form Page 1	Address: 914 VAN BUREN ST	Local Designation #	SHPO #