

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 114 WASHINGTON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 08 N	Longitude: 122 36 32 W
Township: 02S	Range: 02E	Section: 31	Block: 92 Lot: 7
Date of Construction: c. 1920	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 vinyl; large fixed picture window	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Front porch appears to be an alteration of full width; full window replacement; rear gabled addition; garage inserted underneath building			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This single story bungalow has a rectangular plan with a basement level garage, a front gable addition, a back gable addition and a carport. It sits on a concrete foundation and is clad in asbestos shingles. The bargeboard is notched for brackets, but several are missing. The front gabled roof is covered with composition shingling. The windows are primarily 1/1 vinyl with a large picture window above the garage. The front porch has been greatly altered. The southwest side has a projecting gable that has been enclosed with a recess for the door. The northwest side with the picture window has an open porch with a wrought iron rail created over the lower garage projection. The front stairs are concrete with built-in planters and assorted handrails. There is a concrete block retaining wall.			
Statement of Significance:			
Researcher/Organization: Carin Petersen / HPNW			Date Recorded: 5/11/2002
Survey Form Page 1	Address: 114 WASHINGTON ST	Local Designation #	SHPO #