

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 509 WASHINGTON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 20 N	Longitude: 122 36 23 W
Township: 02S	Range: 02E	Section: 31	Block: 55 Lot: 2x Map #: 22E31AC Tax Lot #: 2700
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow / Colonial		Plan Type/Shape: Rectangle	Number of Stories: 1.5
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; 5/1 fixed	
Exterior Surface Materials Primary: Lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Full siding replacement; window surrounds have been replaced			
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This 1-1/2 story bungalow has a rectangular plan with a shed projection to the north. It sits on a concrete foundation and is clad in a lapped fiberboard. The side gabled roof is covered with composition shingling. There are boxed eaves and eave returns on both the main roof and the porch roof. The windows are primarily 1/1 wooden double-hung with 5/1 fixed on the front elevation. The front porch has a gabled roof supported by tapered box columns and a blank frieze. The porch railing is sided and the stairs are to the north side. There is a picket fence surrounding the front yard.			
Statement of Significance:			
Researcher/Organization: Carin Petersen / HPNW			Date Recorded: 5/11/2002
Survey Form Page 1	Address: 509 WASHINGTON ST	Local Designation #	SHPO #