

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 110 WASHINGTON ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 08 N	Longitude: 122 36 33 W
Township: 02S	Range: 02E	Section: 31	Block: 92 Lot: 6
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Wood shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Post-war siding; concrete foundation; plywood soffit			
Number and Type of Associated Resources: Garage at rear (1)			
Integrity: Good		Condition: Good	Local Ranking:
			National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This single story bungalow has a rectangular plan with a detached garage in back. It sits on a board formed concrete foundation and is clad in non-original wide wood shingles. There is a wide bargeboard with brackets connecting to a plywood soffit. The front gabled roof is covered with composition shingling. The windows are primarily 1/1 wooden double-hung with lamb's tongues. The front porch is poured concrete, with concrete stairs and a wrought iron railing. The gabled porch roof is supported by two sets of posts to either side of the stair. There is also a concrete retaining wall. The gabled garage in the rear is clad in the same shingling.			
Statement of Significance:			

Researcher/Organization: Carin Petersen / HPNW		Date Recorded: 5/11/2002	
Survey Form Page 1	Address: 110 WASHINGTON ST	Local Designation #	SHPO #