

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 115 S CENTER ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 07 N	Longitude: 122 36 40 W
Township: 02S	Range: 02E	Section: 31 Block: 81 Lot: 3	Map #: 22E31CA Tax Lot #: 2300
Date of Construction: c. 1930	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 3/1 wood double-hung; aluminum sliders	
Exterior Surface Materials Primary: Bevel (lap)		Secondary: Wood shingle	Decorative:
Exterior Alterations or Additions/Approximate Date: Wood shingles on north and south sides; window replacement on south side.			
Number and Type of Associated Resources: Garage to SW (1)			
Integrity: Fair Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story minimal tract-style house has a rectangular plan and sits on a poured concrete foundation. The gable roof is covered in composition shingles and pointed barge boards. The gable roof of the front porch is supported by decorative brackets. The front façade of the house, and the knee wall and gable end of the front porch are covered in narrow lap siding. The remaining facades of the house are covered in wide lap siding. Windows are 1/1 wood double-hung and aluminum sliders. The gable roof entry porch has eave returns and is supported by posts. A detached garage is on the south side of the house.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 5/10/2002	
Survey Form Page 1	Address: 115 S CENTER ST	Local Designation #	SHPO #