

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 319 S CENTER ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 01 N	Longitude: 122 36 46 W
Township: 02S	Range: 02E	Section: 31 Block: 79 Lot: 4	Map #: 22E31CA Tax Lot #: 7800
Date of Construction: c. 1900	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung; picture; vinyl sliders	
Exterior Surface Materials Primary: Cementitious lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Shed roof addition on rear (west) façade; hipped roof addition to the south; full window replacement; full siding replacement			
Number and Type of Associated Resources: None			
Integrity: Fair	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story transitional style house has a rectangular plan and sits on a poured concrete foundation. The gable roof is covered in composition shingles and is pierced by a large shed dormer. The house is covered with lap siding grounded by a water table with cap. Windows are primarily 1/1 wood double-hung, vinyl slider and picture. The inset porch has a knee wall and columns supporting the roof. The north façade has a gable roof bay. A shed roof addition is on the rear (west) façade. There is a hipped roof addition to the south façade.			
Statement of Significance:			

Researcher/Organization: Heather Goodson / HPNW		Date Recorded: 4/6/2002	
Survey Form Page 1	Address: 319 S CENTER ST	Local Designation #	SHPO #