

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>110 S HIGH ST</b>		City: <b>OREGON CITY</b>	
USGS Quad Name: <b>Oregon City</b>		GPS Latitude: <b>45 21 09 N</b>	Longitude: <b>122 36 41 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b> Block: <b>81</b> Lot: <b>7</b>	Map #: <b>22E31CA</b> Tax Lot #: <b>2700</b>
Date of Construction: <b>c. 1925</b>	Historic Name:	Historic Use or Function: <b>Domestic - single dwelling</b>	
Grouping or Cluster Name: <b>NA</b>	*Current Name or Use: <b>Domestic - single dwelling</b>	Associated Archaeological Site: <b>Unknown</b>	
Architectural Classification(s): <b>Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>	Number of Stories: <b>1.0</b>
Foundation Material: <b>Unknown</b>		Structural Framing: <b>Unknown</b>	Moved? <b>No</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Fixed, vinyl, picture window; 1/1 vinyl double-</b>	
Exterior Surface Materials Primary: <b>Vertical groove plywo</b>		Secondary: <b>Lap</b>	Decorative:
Exterior Alterations or Additions/Approximate Date: <b>Vertical groove plywood; full window replacement</b>			
Number and Type of Associated Resources: <b>None</b>			
Integrity: <b>Poor</b> Condition: <b>Good</b>		Local Ranking:	National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Not 50 years old <input checked="" type="checkbox"/> Irretrievable loss of integrity			
Description of Physical and Landscape Features:			
This one story bungalow has a rectangular plan and sits on a concrete foundation with vertical tongue and groove skirting. The gable roof is covered with composition shingles and has decorative eave brackets. The walls are clad in vertical groove plywood, with lap siding on the gable ends. Windows are primarily 1/1 wood double-hung. There is a large fixed picture window on the west façade. The gabled-roof front porch has a vertical wood knee wall, and combined vertical and lap wood siding in the gable end. There is a concrete retaining wall with integrated steps.			
Statement of Significance:			

Researcher/Organization: <b>Heather Goodson / HPNW</b>		Date Recorded: <b>5/10/2002</b>	
<b>Survey Form Page 1</b>	Address: <b>110 S HIGH ST</b>	Local Designation #	SHPO #