

## OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: <b>911 9TH ST</b>		City: <b>OREGON CITY</b>		
USGS Quad Name: <b>Oregon City</b>		GPS	Latitude: <b>45 21 23 N</b>	Longitude: <b>122 36 01 W</b>
Township: <b>02S</b>	Range: <b>02E</b>	Section: <b>31</b>	Block: <b>127</b>	Lot: <b>3x, 4x</b>
Date of Construction: <b>c. 1930</b>		Historic Name:		Historic Use or Function: <b>Domestic - single dwelling</b>
Grouping or Cluster Name: <b>NA</b>		*Current Name or Use: <b>Domestic - single dwelling</b>		Associated Archaeological Site: <b>Unknown</b>
Architectural Classification(s): <b>Minimal Tract / Bungalow</b>		Plan Type/Shape: <b>Rectangle</b>		Number of Stories: <b>1.0</b>
Foundation Material: <b>Concrete</b>		Structural Framing: <b>Unknown</b>		Moved? <b>Yes</b>
Roof Type/Material: <b>Gable / Composition shingle</b>		Window Type/Material: <b>Fixed picture</b>		
Exterior Surface Materials Primary: <b>Lap</b>		Secondary:	Decorative:	
Exterior Alterations or Additions/Approximate Date:		<b>Partial window replacement; open porch gable; lattice work below porch.</b>		
Number and Type of Associated Resources: <b>None</b>				
Integrity: <b>Poor</b>	Condition: <b>Good</b>	Local Ranking:		National Register Listed? <b>No</b>
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district				
Not Eligible: <input type="checkbox"/> Intact but lacks distinction				
<input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old				
Description of Physical and Landscape Features:				
<p>This single story Minimal Tract has a rectangular plan that rests on a poured concrete foundation. Its side facing gable roof is covered with composition shingles and the exterior walls are clad in lap siding. Windows are primarily wood, single pane fixed. The half width porch has an open gable with timbering, which is supported by wood posts. Characteristics of the bungalow style include the wide eaves, with bargeboards and brackets, and the cornerboards. Alterations include a partial window replacement, the lattice work below the porch, and the "opening" of the front porch gable. This house is set back from the street.</p>				
Statement of Significance:				
Researcher/Organization: <b>Sally Wright / HPNW</b>		Date Recorded: <b>9/19/2002</b>		
<b>Survey Form Page 1</b>	Address: <b>911 9TH ST</b>		Local Designation #	SHPO #