OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: **111 S CENTER ST**			City: **OREGON CITY**	
USGS Quad Name: **Oregon City**		GPS Latitude: **45 21 08 N**		Longitude: **122 36 39 W**
Township: **02S** Range: **02E**	Section: **31** Block: **81**	Lot: **2**	Map #: **22E31CA**	Tax Lot #: **2400**

Date of Construction: **c. 1920**	Historic Name:	Historic Use or Function: **Domestic - single dwelling**
Grouping or Cluster Name: **NA**	*Current Name or Use: **Domestic - single dwelling**	Associated Archaeological Site: **Unknown**

Architectural Classification(s): **Bungalow**	Plan Type/Shape: **Rectangle**	Number of Stories: **1.5**
Foundation Material: **Concrete**	Structural Framing: **Unknown**	Moved? **No**
Roof Type/Material: **Jerkinhead / Composition shingle**	Window Type/Material: **6/1 wood double-hung; 6/1 wood fixed**	

Exterior Surface Materials Primary: **Stucco** Secondary: Decorative:

Exterior Alterations or Additions/Approximate Date: **Stucco surfacing; metal railing on porch**

Number and Type of Associated Resources: **Garage (1)**

Integrity: **Fair** Condition: **Good**	Local Ranking:	National Register Listed? **No**

Potentially Eligible: ☐ Individually or ☐ As a contributing resource in a district

Not Eligible: ☐ Intact but lacks distinction

☑ Altered (choose one): ☐ Reversible/Potentially eligible individually or in district

☐ Reversible/Ineligible as it lacks distinction

☑ Irretrievable loss of integrity

☐ Not 50 years old

Description of Physical and Landscape Features:

This 1-1/2 story side-jerkinhead bungalow has a rectangular plan and sits on a poured concrete foundation. The jerkinhead roof is covered in composition shingles with eave returns, has a large shed roof dormer, and is pierced by a chimney. The house is covered in stucco. Windows are multi-pane over one wood double-hung. The gable roof entry porch has eave returns and is supported by broad columns.

The detached garage is also covered in stucco.

Statement of Significance: