

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 914-920 MONROE ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS	Latitude: 45 21 23 N
Longitude: 122 35 58 W			
Township: 02S	Range: 02E	Section: 32	Block: 142 Lot: 7x
Map #: 22E32BC	Tax Lot #: 6000		
Date of Construction: 1946	Historic Name:		Historic Use or Function: Domestic - single dwelling
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - duplex		Associated Archaeological Site: Unknown
Architectural Classification(s): Minimal Tract		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete block		Structural Framing: Unknown	Moved? No
Roof Type/Material: Hip / Composition shingle		Window Type/Material: 2/2 wood double-hung	
Exterior Surface Materials Primary: Metal		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date:		Modern front doors and handrails	
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Good	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district			
Not Eligible: <input type="checkbox"/> Intact but lacks distinction			
<input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
<p>This c.1946 residence is a multi-unit complex of three apartments. There are two structures, one facing the street and the other detached behind the main structure. The main structure is a duplex and is square in plan with a hipped roof. The smaller single unit behind has a rectangular plan with a gabled roof. The windows are typically a 2/2 wood double-hung with 1/1 wood double-hung in some locations. A fixed 6-pane picture window is present on the front elevation of the duplex. Alterations include the addition of concrete steps and a metal handrail leading up to the duplex structure from the street. A brick half wall exists at the front elevation</p>			
Statement of Significance:			

Researcher/Organization: Christy Fockler / HPNW		Date Recorded: 4/12/2002	
Survey Form Page 1	Address: 914-920 MONROE ST	Local Designation #	SHPO #