

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 104 TUMWATER DR		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS	Latitude: 45 21 10 N
Longitude: 122 36 44 W			
Township: 02S	Range: 02E	Section: 31	Block: NA Lot: NA
Map #: 22E31CA	Tax Lot #: 3500		
Date of Construction: c. 1945	Historic Name:		Historic Use or Function: Other - unknown
Grouping or Cluster Name: NA	*Current Name or Use: Social - club		Associated Archaeological Site: Unknown
Architectural Classification(s): Quonset		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Barrel Vault / Metal standing seam		Window Type/Material: 2/2 double-hung	
Exterior Surface Materials Primary: Drop		Secondary: Plywood	Decorative:
Exterior Alterations or Additions/Approximate Date: Entry added, west side.			
Number and Type of Associated Resources: None			
Integrity: Good	Condition: Fair	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH			
Description of Physical and Landscape Features:			
This building is a quonset hut serving as the American Legion Post 5 and the V.F.W. #1324. The building sits at the southeast corner of a large parking lot, with a rectangular bay added to the west side that houses the entry to the building. The main building is oriented north-south, and the arched roof is mirrored in the arched parapet on the entry wing. The entry is clad with plywood, while the north and south ends of the building are clad with drop siding. Two shed dormers on the west side house banks of five 2/2 double-hung wood sash windows with horizontally oriented panes and narrow trim molding. A small shed roof is cantilevered out from the north end of the building over an emergency exit.			
Statement of Significance:			

Researcher/Organization: Alex McMurry / HPNW		Date Recorded: 7/26/2002
Survey Form Page 1	Address: 104 TUMWATER DR	Local Designation #
		SHPO #