

**OREGON INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE INVENTORY FORM**

HISTORIC NAME: Edward Martin Residence DATE OF CONSTRUCTION: c. 1892
COMMON NAME: _____ ORIGINAL USE: Residence
ADDRESS: 413 Willamette Street PRESENT USE: Residence
OWNER: David and Susan Madsen, 413 Willamette St. ARCH./BLDR.: Waldron (bldr.?)
STYLE: Queen Anne Vernacular
T/R/S: 2-2E-32CB TAX LOT: 11900 BLDG. STRUC. DIST. SITE OBJ. (CIRCLE)
ADDITION: Mount Pleasant Addition THEME: Architecture, 19th Century
LOT: 12 BLOCK: 3 QUAD: Oregon City

PLAN TYPE/SHAPE: Square NO. OF STORIES: 2 1/2
FOUNDATION MATERIAL: Post and block BASEMENT (Y/N): No
ROOF FORM & MATERIALS: Cross-gable. Composition.
WALL CONSTRUCTION: Wood STRUCTURAL FRAME: Stud
PRIMARY WINDOW TYPE: One-over-one double-hung with wide trim with slight ears.
SURFACING MATERIALS: Shiplap siding. Two-story corner pilasters with capitals.
DECORATIVE FEATURES: Fishscale and diamond shingles in west and south gables. Gable
OTHER: returns detailed by very ornate scroll brackets. Front slanted bay with band trim.
CONDITION: EXCELLENT _____ GOOD _____ FAIR _____ DETERIORATED X MOVED _____ (date)
EXTERIOR ALTERATIONS/ADDITIONS (dated): Front door is not original, n.d.

NOTEWORTHY LANDSCAPE FEATURES: None.

ASSOCIATED STRUCTURES: None.

KNOWN ARCHAEOLOGICAL FEATURES: None.

GEOGRAPHIC SETTING: Occupies an interior lot of Willamette Street, just one block from its intersection with busy commercial Molalla Avenue. The adjacent lot fronting on Molalla Avenue is occupied by an apartment building. Other buildings on Willamette Street are single-family residences. No other landmark buildings on Willamette Street.

STATEMENT OF SIGNIFICANCE: (Historical and/or architectural importance, dates, events, persons, contexts): No biographical information was found on Edward Martin, the purported original owner of the house. One neighbor claims this house was built by the E.J. Waldron family, who owned a sawmill and used the best of the lumber from it to build the house. This would date the house to around 1905. The house is significant for its unusual architectural detailing and its age. Nearly all of the house's details are intact, but it is in very poor repair, and has no paint.

SOURCES: Sanborn Insurance Map, 1900. Pioneer National Title Company Records, Oregon City. Interview with Mrs. Jackson, by Pat Erigero, 1982.

NEGATIVE NO: Roll P, #4, 5
SLIDE NO: _____

RECORDED BY: Patricia Erigero
DATE: May 1982

SHPO INVENTORY NO.: _____

OREGON INVENTORY OF HISTORIC PROPERTIES
HISTORIC RESOURCE INVENTORY FORM - TWO

NAME: Edward Martin Residence

T/R/S: 2-2E-32CB TAX LOT 11900



ADDRESS: 413 Willamette Street

QUADRANGLE: Oregon City



NEGATIVE NO. Roll P, #4, 5

SLIDE NO. _____



GRAPHIC AND PHOTO SOURCES: Base Map of Oregon City, 1987.
Oregon City Planning Department Photograph, 1987.

SHPO INVENTORY NO.: _____