

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 401 2ND ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 13 N	Longitude: 122 36 37 W
Township: 02S	Range: 02E	Section: 31 Block: 35 Lot: 5x	Map #: 22E31AC Tax Lot #: 13000
Date of Construction: c. 1910	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): American Foursquare		Plan Type/Shape: Square	Number of Stories: 2.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Hip / Composition shingle		Window Type/Material: 1/1 wood double-hung	
Exterior Surface Materials Primary: Asbestos shingle		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Resided in asbestos ceramic shingles over round-edge drop; enclosed sleeping porch			
Number and Type of Associated Resources: Garage to east (1)			
Integrity: Fair	Condition: Fair	Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input checked="" type="checkbox"/> Altered (choose one): <input checked="" type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			IMAGE UNAVAILABLE SEE ORIGINAL SURVEY FORM FOR PHOTOGRAPH
Description of Physical and Landscape Features:			
This two story American Foursquare-style house is square in plan and sits on a concrete block foundation. The flared hip roof is covered in composition shingles. Shaped modillions support the eave. The house is covered with asbestos ceramic shingle siding. Windows are primarily 1/1 wood double-hung. A hip roofed entry porch has large columns and a knee wall. There is a bracketed hood on the east entry. A rear sleeping porch has been enclosed. The front door is the original 3-panel door. There is an exterior chimney on the west side. There is a detached garage on the east side of the house.			
Statement of Significance:			
Researcher/Organization: Heather Goodson / HPNW			Date Recorded: 4/12/2002
Survey Form Page 1	Address: 401 2ND ST	Local Designation #	SHPO #