

OREGON CITY HISTORIC RESOURCE SURVEY FORM

Street Address: 706 4TH ST		City: OREGON CITY	
USGS Quad Name: Oregon City		GPS Latitude: 45 21 12 N	Longitude: 122 36 23 W
Township: 02S	Range: 02E	Section: 31 Block: 105 Lot: 8x, 7x	Map #: 22E31AC Tax Lot #: 8600
Date of Construction: c. 1925	Historic Name:	Historic Use or Function: Domestic - single dwelling	
Grouping or Cluster Name: NA	*Current Name or Use: Domestic - single dwelling	Associated Archaeological Site: Unknown	
Architectural Classification(s): Bungalow		Plan Type/Shape: Rectangle	Number of Stories: 1.0
Foundation Material: Concrete		Structural Framing: Unknown	Moved? No
Roof Type/Material: Gable / Composition shingle		Window Type/Material: 1/1 wood double-hung, fixed	
Exterior Surface Materials Primary: Lap		Secondary:	Decorative:
Exterior Alterations or Additions/Approximate Date: Concrete retaining wall at driveway, c. 1960			
Number and Type of Associated Resources: None			
Integrity: Good Condition: Good		Local Ranking:	National Register Listed? No
Potentially Eligible: <input type="checkbox"/> Individually or <input checked="" type="checkbox"/> As a contributing resource in a district Not Eligible: <input type="checkbox"/> Intact but lacks distinction <input type="checkbox"/> Altered (choose one): <input type="checkbox"/> Reversible/Potentially eligible individually or in district <input type="checkbox"/> Reversible/Ineligible as it lacks distinction <input type="checkbox"/> Irretrievable loss of integrity <input type="checkbox"/> Not 50 years old			
Description of Physical and Landscape Features:			
This one story house sits under a side gable roof with a second gable projecting out from the north side of the house to cover the main entry. A shed roof extension of the main gable covers the east end of this porch, where the eave is supported by tapered square columns set on a solid balustrade. The balustrade, like the rest of the house, is clad with lap siding. The gables feature open eaves with wide barge boards and knee brackets. The windows are predominantly 1/1 double-hung wood sash, but the north side windows have been replaced with fixed wood sashes. A one car garage is set into the house at the basement level on the northeast corner, featuring six-pane-over-three-panel out-swinging doors. The retaining walls lining the driveway are replacements of the original walls. A low basalt retaining wall faces the street on the north side of the house, which also features an exterior chimney and cantilevered bay on the east side.			
Statement of Significance:			
Researcher/Organization: Alex McMurry / HPNW			Date Recorded: 3/25/2002
Survey Form Page 1	Address: 706 4TH ST	Local Designation #	SHPO #